


Inconsistency in velocity




POSSIBLE CAUSE: Wrong matching between paintball and barrel.

SOLUTION: Use right size and quality paintball.



SOLUTION: Needs lubrication on striker and bolt.



POSSIBLE CAUSE: Battery has insufficient power.

SOLUTION: Use fresh battery.



POSSIBLE CAUSE: Poorly maintained Inline Regulator.

SOLUTION: Clean and rebuild Inline Regulator.
Replace Inline Regulator Piston & Seat Seal carrier or main spring if necessary.