

## Leaking from the 90 Degree Elbow



Thread Seal Tape

**POSSIBLE CAUSE:** Braided Hose (P071) is loose from the 90 Degree Elbow.

**SOLUTION:** Apply Thread Seal Tape and reconnect Braided Hose to Bottom ASA.