

Leaking from the 90 Macroline Elbow



Thread Seal Tape

POSSIBLE CAUSE: 90 Degree Macroline Elbow is damaged.

SOLUTION: Replace 90 Degree Macroline Elbow.



POSSIBLE CAUSE: Macroline Hose is damaged.

SOLUTION: Replace Macroline Hose.