


Leaking from the Straight Macroline Elbow



Thread Seal Tape

POSSIBLE CAUSE: Straight Macroline Elbow is damaged.

SOLUTION: Replace Straight Macroline Elbow.



POSSIBLE CAUSE: Macroline Hose is damaged.

SOLUTION: Replace Macroline Hose.